Rental Housing Safety Program Year-End Report 2019




March 9, 2020


Overview

- Year-end Registration 2019
- Property Map
- Registered Properties at a Glance
- Inspection/Re-Inspection By Property Type
- Inspection/Re-inspection Results
- Common Inspection Items Failed
- Inspection Quick Facts/Insights
- RHSP Property Improvements
- Inspection of Note
- Looking Forward 2020





Year-end Registration - 2019



Year-end Registration - 2018


 Properties

 Unregistered:
 1,127 (34%)


 Registered:
 2,219 (66%)

Unregistered: 1,970 (15%) Registered: 11,328 (85%)


Registered Properties at a Glance - 2019




2019 Initial Inspections by Property Type



Initial Inspection Results



2019 Re-Inspections by Property Type




Property Re-Inspections – 321

All Re-Inspections Completed By City of Lakewood.


Comparison: 2018 Re-Inspections - 221

279

Re-Inspection Results



Common Inspection Items Failed





Inspection Quick Facts - 2019


- Largest property that passed initial inspection: 56 units (Ridgewood Apts; Chicago Ave.) – Private Inspector
- Largest property that failed initial inspection: 198 units (Arbor Pointe Apts; 105th Ave. SW) – Private Inspector
- Largest property that passed re-inspection: 195 units (Forest Village Apts; Phillips Rd. SW) – City Inspector
- Largest property that failed re-inspection: 55 units (Woodlake Estates; Mt. Tacoma Dr. SW) – City Inspector

Inspection Insights - 2019

Initial Inspection Results – By Property



<u>Re-Inspection Results – By Property</u>



• Village at Seeley Lake Apartments – 9501 59th Ave. SW (520 units)








• Village at Seeley Lake Apartments – 9501 59th Ave. SW (520 units)





• Hawaiian Village Apartments – 40 Thunderbird Pkwy. (99 units)





• Hawaiian Village Apartments – 40 Thunderbird Pkwy. (99 units)





• 8410 S. Tacoma Way (5 units)



• 8410 S. Tacoma Way (5 units)



• 8410 S. Tacoma Way (5 units)






• 8410 S. Tacoma Way (Abandoned Contractor Yard)



• 8816 34th Ave. S (SF Rental)





• 9027 Meadow Rd. SW (SF Rental)





Common Repairs



Inspection of Note

• Crown Pointe – 2608 to 2704 84th St. Ct. S (77 units)



Looking Forward - 2020

- 2020 Inspection Lottery Letters Mailed February 28, 2020
- 2020 Registration Deadline March 31, 2020
- Enforcement of Noncompliant 2018 Properties Begins April 2019
- Follow-Up With Properties Still Correcting Deficiencies Identified In 2018/2019 Inspections
- Continue Code Violation Triggered Inspections
- Update RHSP Portal
- Monitor Registration/Inspection Trends



QUESTIONS?